

S9_D111_WINDOWS_10_Driver_Note



SXCONF Windows 10 Driver Note

18/09/2017

Changes

Vers.	Date	Description	Auteur
001	18/09/17	Document created	JR

Summary

1	General Introduction.....	4
2	Disable driver signature verification	5


	SXCONF Windows 10 Driver Note	18/09/2017	XAP-BE
---	-------------------------------	------------	--------

1 GENERAL INTRODUCTION


This document shows how to disable Windows 10 driver signature verification to make SXCONF Driver compatible with it.

2 DISABLE DRIVER SIGNATURE VERIFICATION


1- Hold down the SHIFT key and click on “Restart”.




2- Your computer will restart into this menu. Select “Troubleshoot”




3- Select “Advanced options”.




4- Click on “Startup Settings”




5- Click the “Restart” button to restart your PC into the Startup Settings screen.



6- Type “7” or “F7” at the Startup Settings screen to activate the “Disable driver signature enforcement” option.



- 7- Your PC will boot with driver signature enforcement disabled and you will be able to install unsigned drivers.
- 8- Uninstall any installed SXCONF
- 9- Connect the XAP Steering Wheel and update driver from “Drivers USB XAP 2013”
- 10-Check that the XAP Steering Wheel appears as follow in the Device Manager windows



- 11-Install SXCONF